

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 35

Township: 7 North


Range: 1 East

Corner ID: Polk U-25

Monument Description & Remarks: 2½" Iron Pipe. Survey Sign 4.5ft above ground at pt. B

References On File: Victor H. McCauley survey, U.S.D.A. Forest Service (1986), on file in Surveyor Office & Marston R. Fowler Jr. survey, James Graves, on file in Auditor Office

RECOVERY TIE DRAWING
Field Book 41 Page No. 33



A - 2½" Iron Pipe
B - West 0.73' to Survey
Sign on metal fence post
C - S 86° W 53.45' to MAG
nail in 24" Black Walnut
D - N 65° W 72.70' to Concrete
INDOT ROW, 4"x4"x18"

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 29th day of August, 2008.

Kevin Enright




Administered by the Monroe County Surveyor Review Board

Date: 10/7/2008

T. 7N R. 1E 2nd Mer N.F. Hoosier County Monroe State Indiana
South Section Corner common to sections 35 36 and

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1811</u>		Year of search <u>1986</u> By <u>V.H.M. & R.A.G.</u>	
Original monument <u>Wood Post</u> (wood post, stone, pile of stones, pile, etc.)		Monument found <u>None</u>	
Bearing Trees Species <u>Beech</u> <u>Hickory</u> Diameter <u>24"</u> <u>10"</u> Bearing <u>S 73 W</u> <u>S 74 E</u> Distance <u>14 Lks.</u> <u>27 Lks.</u>		Original Bearing Trees Found Species _____ Diameter _____ Bearing _____ Distance _____	
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed <u>1859</u> By <u>James W. Spencer</u>		Year of search <u>1986</u> By <u>V.H.M.</u>	
Where filed or recorded <u>Monroe Co. Survey Books Pg. 10</u>		None	
Monument _____ (original, concrete post, iron rod, etc.)		_____	
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species <u>Beech</u> <u>Beech</u>		_____	
Diameter <u>24"</u> <u>20"</u>		_____	
Bearing <u>S 75 W</u> <u>N 59 W</u>		_____	
Distance <u>14 Lks.</u> <u>50 Lks.</u>		_____	



Sketch

O Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Fence line and old road bed to west. Corner location is at west edge of roadway embankment & cone. Paved side ditch. If any corner monument was in this vicinity, it is destroyed.

At time of search:

Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. chaining

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes _____ No X

5. Signature V.H.M. McCaul

Perpetuation Record

Monument and accessories established. Include brief description of area.

Set 36" aluminum monument

Accessories Established

Walnut	N.E. Corner	I.S.H.C.	Centerline
22"	Barn	R/W Mon.	Concrete Ditch
S 82 W	N 78 W	N 59 W	East
54.1'	150.6'	72.6'	23.0'

Certified corner restoration certificate prepared.

Yes X No _____

Filed in county records at _____

Date _____ County Document No. _____

Identified on aerial photo No. _____

Which is filed at _____

T. 7N R. 1E Mer. N.F. Section Corner common to sections 35 36 and 37 State Illinois

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed		Year of search	<u>1972</u> By <u>H. Denton</u>
Original monument	<u>wood post</u> (Wood post, stone, pile of stones, pipe, etc.)	Monument found	<u>No</u>
Bearing Trees		Original Bearing Trees Found	
Species		Species	
Diameter		Diameter	
Bearing		Bearing	
Distance		Distance	
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed	<u>1859</u> By <u>James Spencer</u>	Year of search	<u>1972</u> By <u>H. Denton</u>
Where filed or recorded	<u>Monroe Co Survey Bk. B 10</u>		
Monument			
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species	<u>Beech</u> <u>Burch</u>		
Diameter	<u>24"</u> <u>20"</u>		
Bearing	<u>S 75 W</u> <u>N 54 W</u>		
Distance	<u>14 lks</u> <u>50 lks</u>		

Relation of Evidence to Record Features Along Section Lines

Section line to sections	Object	Record distance	Measured distance
<u>36-1</u> <u>36-2</u> <u>36-1</u> <u>35-2</u>	<u>Creek 30 lks wide S NW Cor Sec 1</u> <u>Road</u> <u>CK 8 lks wide S</u>	<u>9 ch. E</u> <u>32 lks E</u> <u>6.43 ch E</u> <u>6 ch W</u>	

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Local residence informed us a stone was set at this corner. The new S.R. #446 has been built over the stone. It is buried under 35 feet of fill dirt. We plan to contact the Engineer for the State Hwy. - St. Hwy 446 plans show approx. sec. cor location at 148.9 Ft Lt. of Sta 460+63. They will not monument this one because location is not positive.

Perpetuation Record

Monument and accessories established. Include brief description of area.

New Monument placed by State Hwy.

At time of search:

1. Did you have the record description?
Yes ☒ No ☐

2. How was search area located?

Pacing, chaining, photos, maps,
etc. photos and maps3. Man hours spent in search 1/2 hr4. Do you think additional search might
recover evidence? Yes ☐ No ☒Stone is buried under
Highway5. Signature H. DentonCertified corner restoration certificate prepared: Yes ☐ No ☐

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. Z-21
(Alphabetical-Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 7N R. 1E 2nd Mer. N.F. Monroe County Monroe State Louisiana
Section Corner common to sections 35, 36, and

EXISTING SURVEYS

Original Government Survey

Year surveyed
Original monument wood post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Beech Beech
Diameter 24" 10"
Bearing S 73° W S 70° E
Distance 14 lks 27 lks

Subsequent Corner Restoration

Year surveyed 1859 By James Spencer
Where filed or recorded Monroe Co Survey Bk. 8 p 10
Monument
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Beech Beech
Diameter 24" 20"
Bearing S 73° W N 59° W
Distance 14 lks 50 lks

Original Evidence Found

Year of search 1972 By H. Dorton
Monument found No

Original Bearing Trees Found

Species
Diameter
Bearing
Distance None


Evidence of Subsequent Corner Restoration Found

Year of search 1972 By H. Dorton
None

Bearing Trees, Reference Objects

Species
Diameter
Bearing
Distance

2N 1E



Sketch

☐ Corner ☒ F.S. Land

Sec. 36

At time of search:

1. Did you have the record description?

Yes ☒ No ☐

2. How was search area located?

Pacing, chaining, photos, maps,

etc. photos and maps

3. Man hours spent in search 1/2 hr

4. Do you think additional search might recover evidence? Yes ☐ No ☒

Stone is buried under Highway

5. Signature H. Deaton

Relation of Evidence to Record Features Along Section Lines

Section line to sections	36-1	36-2	36-1	35-2
Object	Creek 30 ft wide-S	HW Cor Sec 1	Road	CK-8 ft wide-S
Record distance	9 ch. E	321 LKs E	6.43 ch E	6 ch-W
Measured distance				

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Local residence informed us a stone was set at this corner. The new S.R. #446 has been built over the stone. It is buried under 35 feet of fill dirt. We plan to contact the Engineer for the State Hwy. - St. Hwy 446 plans show approx. sec. cor location at 148.9 ft Lt. of Sta 466+163. They will not monument this one because location is not positive.

Perpetuation Record

Monument and accessories established. Include brief description of area.

New Monument placed by State Hwy.

Certified corner restoration certificate prepared: Yes ☐ No ☐

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____